

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-124-A-43	Installation of Radio Sets SCR-510-( ), SCR-610-( ), SCR-284-( ) in Truck, 1½ Ton, 6 x 6, Weapons Carrier	12-8-42
D-125-C-43	Pilot Model Suppression Inspection of 1½ Ton, 4 x 4, Cab over Engine, Stake Body, Model G-7123, C.n. No. W-398-qm-13383, Serial No. 9NN224267 at Chevrolet	11-30-42
D-126-C-43	Radio Noise Interference Test on Pilot Model T-53, Gun Carrier, Manufactured by Chrysler Corp. Detroit, Michigan	11-19-42
D-127-E-43	Proposed Preliminary test of oil impregnated paper di-o- Electric Capacitors for Determining proper Electrical and Physical Comparisons to be made with Mica DI-O- Electric Capacitors	12-9-42
D-128-E-43	Status of Noise Suppression Capacitors as Manufactured for P. K. Mallory & Co. by John E. Fast & Company	12-9-42
D-129-C-43	Survey of Application of Proposed type schedule to high tension Ignition Circuit on Vehicle for Purpose of Radio Noise Suppression	12-9-42
D-130-C-43	CANCELLED	
D-131-C-43	Repeatability test on Cadillac Light Tank Model M5A1	12-10-42
D-132-A-43	Provisions required for Installation of Radio Sets SCR-510-( ), SCR-593-( ) and BR-19 in Half Track, Multiple Gun Motor Carriage, M13	12-11-42
D-133-A-43	Installation of Radio Set SCR-610-( ) in Truck, ¾ Ton, 4 x 4, Weapons Carrier	12-14-42
D-134-E-43	Inspection and Test of Experimental all Steel Medium Tank-Track T-54E1	12-14-42
D-135-E-43	Inspection & Test of Experimental All Steel Medium Tank Track T-56E1	12-14-42
D-136-A-43	Provisions required for Installation of Radio Sets SCR-510-( ) in Half Track, 81mm Mortar Motor Carrier M4	12-14-42
D-137-E-43	Status of Filters FL-12 & FL-14 with Flat Steel Terminals as Mfg. by the Solar Mfg. Co.	12-12-42
D-138-D-43	Modification of test equipment and procedure in Prod. Radio Noise Suppression Inspection Screen Room at Dodge Lynch Road Plant	12-15-42

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-139-C-43	Prod Pilot Model Inspection of Suppression of Amphibian, Model DUKW-335, Serial No. 010, Contract No. W-2425-gm-234, Mfg. by Yellow Truck & Coach, Pontiac, Michigan	11-22-42
D-140-E-43	Report of Liaison Work between the S. C. Gen. Dev. Lab. on the Ord. Dept. at the Proving Center Aberdeen Proving Grounds, Maryland, from Sept 9, 1942 to Nov. 15, 1942.	12-16-42
D-141-C-43	CANCELLED	
D-142-C-43	CANCELLED	
D-143-C-43	R. N. I. Test on Universal Carrier, (Bren Gun Carrier) GAU (T-16), Serial No. 2, Manufactured by the Ford Motor Company, Dearborn, Michigan	12-16-42
D-144-E-43	Status of Noise Suppress Filters FL-12 and FL-14 as Mfg. by the Sprague Specialties Company	12-23-42
D-145-C-43	Radio Noise Interference Test on Prod. Model Armored Car T-17E1 Manufactured by Chevrolet Division, General Motors Corp.	12-18-42
D-146-C-43	Production Pilot Model Inspection of 1½ Ton, 4 x 2 Cab and Chassis, Model E. F., Serial No. EF-1-S-5049, Cont. No. DA-TPS-8730 at the Plant of Mack Mfg. Corp., Allentown, Pa.	11-12-42
D-147-C-43	CANCELLED	
D-148-C-43	CANCELLED	
D-149-C-43	Pilot Model Insp. of Suppression as Applied to the 1/4 Ton, 4 x 4, Model GPA Amphibian, Serial No. 1565, Cont. No. W-398-gm-12937, Mfg. by Ford Motor Company, Dearborn, Michigan	11-23-42
D-150-C-43	Production Pilot Model Inspection of 1½ Ton, 4 x 2, Cab and Chassis, Model No. E. G., Serial No. 1-5-2716, Cont. No. DA-TPS-8730 at the plant of the Mack Truck Corp., Allentown, Pa.	11-14-42
D-151-E-43	Inspection and Test of Experimental Rubber & Steel Half Track T-57E1 by Goodyear Rubber and Tire Co.	12-23-42
D-152-C-43	Suppression of Windshield Wiper Motor on Hunter Hatch Hood Assembly designed for Medium M-4 Tank	12-22-42

	Mfg. by Sprague Specialties Co.	
D-154-E-43	Test on Random Samples of Radio Noise Suppression Filters (Mallory & Fast)	12-24-42
D-155-E-43	Effect of Capacity on Insertion Loss Characteristics of New Type RNE Low Inductance Capacitors	12-28-42
D-156-C-43	Insp. of Experimental Suppression System on $\frac{1}{2}$ Ton, 4 x 4, Reconnaissance Truck, equipped with Terminal Box, Serial No. 127614, Contract No. W-398-qm-13117 Mfg. by Willys-Overland Company, Toledo, Ohio	12-24-42
D-157-C-43	CANCELLED	
D-158-C-43	Suppression of ODOGRAPH (CONFIDENTIAL)	12-19-42
D-159-E-43	Mechanical & Electrical Characteristics of the New Universal Mounting Bracket as Designed for the RNE-CD Low Inductance Capacitor	12-28-42
B-160-E-43	Test on Production Samples of Special FL-13 Filter (Tobe Deutschmann Part Number 1152) as Mfg. by Tobe Deutschmann Corp.	1-7-43
D-161-E-43	Installation of Test of Experimental Rubber and Steel Med. Tank Tracks T-48ELA & T-48ELB	12-29-43
D-162-C-43	R. F. Attenuation Test Conducted on the Screen Room at the Federal Motor Truck Co., Detroit	12-18-42
D-163-E-43	Test on Random Samples of Radio N. Suppression Filters & Capacitors (Sprague)	1-5-43
D-164-C-43	Experimental Pilot Inspection of Suppr. of 4 Ton, 4 x 4, General Service Cargo Carrier, Model HAR-1, Serial No. D-23, Cont. W-2425-qm-231, at Four Wheel Drive	12-10-42
D-165-E-43	Installation of Radio Set SCR-510-( ) Interphone System RC-99-( ) & British Wireless Set No. in Pilot Production Model of 2 in. Gun Motor Carriage M10A1 Mfg. by Ford Motor Co., Highland Park, Michigan	11-28-42
D-166-E-43	Test of General Electric Company Low Inductance Capacitors	2-2-43
D-167-E-43	Survey of Results of Production Vehicular Suppression Inspection in Dodge Lynch Rd. Plant Screen Rooms Before and After Equipment and Procedure Modification	1-2-43

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-168-D-43	Comparison of Results Obtained with Various Approved Metal-Clad Capacitors Substituted for the Prod. Combination of FL-12 Filter & Metal-Clad Capacitor located at the Generator Armature terminal & the Elimination of the Distributor Breaker Point Filter FL-15 on the GMC-2 $\frac{1}{2}$ Ton, 6 x 6 Vehicles	1-12-43
D-169-C-43	Production Pilot Model Inspection of 7 $\frac{1}{2}$ Ton, 6 x 6 Prime Mover, Model No., Serial No. 8D1011, Cont. No. W-398-qm-11768 & W-2425-qm-654, Mfg. by Mack	12-28-42
D-170-C-43	Production Pilot Insp. of Supp. as Applied to the 4 Ton, 6 x 6, Dump Truck, Model 972 Serial No. 972, Cont. No. W-398-qm-11509, Mfg. by Diamond T Motor Co. Chicago, Illinois	12-17-42
D-171-E-43	Suitability of the General Motors Proving Ground, Milford, Michigan, for Conducting of Track Static Interference Test	1-4-43
D-172-A-43	Prod. Inspection of Radio Noise Suppression System Applied to the Unarmored Tactical Vehicles.	1-4-43
D-173-C-43	Radio Interference Tests on Experimental Pilot Model Pers. Carrier, Half Track, Model M3, USA Registration No. W-4043931, Serial No. M34126, Contract No. W-271-Ord-964, Manufactured by the Diamond T. Motor Co. Chicago	12-31-42
D-174-C-43	Pilot Model Inspection of Suppression as Applied to the 5 Ton, 4 x 2, Model EH, Prime Mover, Serial No. E.H.I.D. 3977-Contract Nos. W-2425-qm-230 and W-670-ord-3191 mfd. by Mack Mfg. Co., Pennsylvania	12-29-42
D-175-C-43	Radio Noise Interference Test on Production Model Armored Car T-17E1 Mfg. by Chevrolet	1-5-43
D-176-E-43	Comparison of Tobe Deutschmann Modified 1107-SDE Shielding Box with Signal Corps Shielding Box SCD-8077-C	1-6-43
D-177-C-43	Production Pilot Inspection of Suppression as Applied to the 40 Ton, 6 x 4, Diesel Tank Transport, Model 981, Serial No. 981, Contract No. W-398-qm-11594 Mfg. by Diamond T	12-20-42
D-178-C-43	Prod. Pilot Inspection of Suppression as Applied to the $\frac{1}{2}$ Track, Model M5, Serial No. M5-569, Contract No. W-271-ORD-126 Mfg. by International Harvester Co.	12-28-42

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-179-C-43	Production Pilot Inspection of Suppression as Applied to the 4 Ton, 6 x 6, Ponton Truck, Model 970, Serial No. 970, Contract No. W-398-qm-11509, Mfg. by Diamond T Motor Company	12-21-42
D-180-C-43	CANCELLED	
D-181-C-43	Experimental Pilot Model Inspection of Suppression as Applied to the 2½ Ton, 6 x 6, Cab over Engine Truck Model No. AFKWX-353, Serial No. 3467, Mfg. by Yellow Truck and Coach Co.	12-12-42
D-182-D-43	CANCELLED	
D-183-C-43	Pilot Model Inspection of Suppression as Applied to Snow Troop Cargo Carrier, Model No. U. S. T-15, Serial No. 37, Contract No. W-271-ORD-1859, Mfd. by Studebaker Corp, South Bend, Indiana	12-26-42
D-184-C-43	CANCELLED	
D-185-C-43	Radio Interference tests on Medium Tank, Model M-7 Serial No. 2-USA. Registration No. W-3095027, Contract No. W-271-Ord-849 mfd. by International Harvester Company--Bettendorf, Iowa	12-22-42
D-186-C-43	Pilot Model Inspection of Suppression as Applied to the 10 Ton, Refrigeration Van, Contract Nos. W-398-qm-13701 and W-670-Ord-3195, Serial No. 38293 mfd. by the Watson Automotive Equipment Co-Baltimore, Maryland and Incorporating a Waukesha Ice Engine Unit (truck type) Model TCU No. 4608 mfd by the Waukesha Mtr. Co. Waukesha, Wisconsin.	12-29-42
D-187-D-43	Procedure for setting limits in production radio noise inspection screen rooms for motor transport vehicles using the revised screen room equipment incorporating the modified Hallicrafters SX-28 receiver	1-9-43
D-188-C-43	Production Pilot Inspection of Suppression as Applied to 5 Ton, 4 x 4, Cargo Carrier Model U.S. 6 x 4 - Serial No. 13761 & DA-W-398-qm-519 mfd. by Studebaker	1-9-43
D-189-A-43	Service test Installation of Radio Set SCR-528-( ) and associated Interphone Equipment in Heavy Tank M6.	1-12-43
D-190-D-43	Radio Noise Inspection Equipment set-up for Prod. SCREEN ROOM testing of Motor Transport Vehicles using Standard (Unmodified) Model SX-28 Hallicrafters or National Model NC-200 Receivers	1-11-43

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-191-E-43	Test on Random Sample of Radio Noise Suppression Components as Mfg. by Mallory	1-12-43
D-192-D-43	Comparison of Approved Metal Clad Capacitor Suppr. System Substituted for the Approved Production Filter Suppr. System on GMC 2½ Ton, 6 x 6 Vehicles.	1-13-43
D-193-E-43	Test on Random Sample of Mallory Radio Suppression Components Mfg. by J. E. Fast Co.	1-14-43
D-194-D-43	Radio Noise Interference Suppression of Electrical Equipment Other Than Ignition and Charging Circuits on Dodge 3/4 Ton, 4 x 4, Ambulance Vehicles	1-18-43
D-195-D-43	Experimental Suppression on Generating Unit, Model No. M7 mfd. by Detroit Wax Paper Co, River Rouge, Michigan	1-16-43
D-196-A-43	Installation of Radio Sets SCR-528-( ), SCR-610-( ) Interphone System RC-99-( ) in Tank Recovery Unit T2	1-18-43
D-197-C-43	Prod. Pilot Model Insp. of Windshield wiper suppr. on Chevrolet Med. Armored Car-Mod. T-17E1, Serial No. AGL2-24-1152, Ord. No. 5916, US No. 6024989 by Chevrolet Motor Car Division, Flint, Michigan. Windshield wiper by Bosch Mfg. Model No. WW-A24-CL87	1-10-43
D-198-E-43	Test on random samples of radio noise suppression capacitors	1-18-43
D-199-C-43	Radio Interference Tests on Pilot Model Medium Tank M4, USA Registration No. W-3010772, Serial No. 1918, Cont. W-670-ORD-1814 mfd by the Baldwin Locomotive Works Eddystone, Pa.	1-12-43
D-200-A-43	Installation provisions for Radio Set SCR-610-( ) & British Wireless Set No. 19 in 105 mm Howitzer Motor Carriage M7 (Amer. Locomotive)	1-19-43
D-201-D-43	Radio Noise Interference Tests on the Generating Unit PE-95, Model WC5RS, Serial No. 101-19859, Mfg. by D. W. Onan & Sons, Mpls, Minn.	2-10-43
D-202-C-43	Radio Noise Interference Test and Insp. of Supp. Components Applied to Pilot Prod. 3 inch Gun Motor Carriage (M10A1) Serial No. 1846, Manufactured by the Ford Motor Company, Highland Park, Michigan	1-16-43
D-203-E-43	Investigation & Track Static Interference Tests Conducted on Production Model ½ Track M-5 Equipped with Timkin Roller Bearings	1-21-43

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-204-E-43	Marking method as applied to Capacitors Mfg. by the Tobe, Deutschmann Corporation	1-16-43
D-205-E-43	Development Test on Low-Inductance Capacitors as mfd by the Cornell-Dubilier Electric Corporation	5-28-43
D-206-E-43	CANCELLED	
D-207-A-43	Installation Check of Zenith British Wireless Standard Set No. 19 & Philco Installation Kit in the Universal Carrier, Full Track T16 (Ford Motor)	1-22-43
D-208-A-43	Installation Check of British Wireless Set No. 19 & Sample Inst. Kit Furnished by Zenith Radio Corp in Armored Car TAI7EL (Chevrolet)	1-21-43
D-209-A-43	Installation Check of Zenith Sample Inst. Kit & British Wireless Set No. 19 in the 57 mm Gun Mtr. Carriage T-48 at Diamond T Motor Company	1-21-43
D-210-E-43	Report of Visit to the Goodrich Tire & Rubber Company Akron, Ohio; Good Year Tire & Rubber Company, Akron Ohio; Timken Roller Bearing Co., Canton, Ohio; Ohio Rubber Company, Willoughby, Ohio	3-13-43
D-211-C-43	Production Pilot Model Inspection of Suppression as Applied to the Armored Car, T-17, Model GQ, Serial No. 2063, Contract No. W-374-ORD-1402, Manufactured by the Ford Motor Company, St. Paul, Minnesota	1-11-43
D-212-C-43	Production Pilot Model Inspection of Suppression as Applied to the 2½ Ton, 6 x 6, Cargo Carrier, Model CCKW-353A1, Serial No. 169804, Contract No. W-398-gm-11595, Equipped with M-32 Gun Mount Manufactured by Yellow Truck and Coach	1-4-43
D-213-C-43	CANCELLED	
D-214-C-43	Inspection of Experimental Suppression as Applied to 2½ Ton, 6 x 6, Cargo Carrier, Model CCKW-353, Serial No. 158351-A1, Contract No. W-398-gm-11595, Manufactured by Yellow Truck and Coach.	1-4-43
D-215-E-43	Status of Laboratory Sample Filters (Delco-Remy Part No. EX-20577) as Manufactured by Delco-Remy	1-30-43
D-216-E-43	Standardization of Capacitor container and bracket as Applied to United States Army Vehicles	1-25-43
D-217-A-43	Revisions to Installation of Radio Set SCR-510-( ) & Interphone Equipment RC-99 in 3 in Gun Motor Carriage M10 & M10A1 (Fisher Tank)	1-25-43

D-218-E-43	Force Measuring Devices observed at Chrysler Corporation, Engr. Lab.	1-26-43
D-219-E-43	Development Test of Low Inductance Capacitors	2-18-43
D-220-E-43	Test on Random Samples of Radio Noise Suppression Components as Manufactured by Delco-Remy GMC	1-27-43
D-221-A-43	Installation Provisions for Radio Sets SCR-508-( ), and SCR-506-( ), British Wireless Set No. 19 and Interphone in Medium Tank T23 at the Erie Works of the General Electric Company	1-28-43
D-222-C-43	Production Pilot Model Inspection of Experimental Suppression as Applied to the Light Tank M5A1 Serial No. 3531 U.S.A. Registration No. W-3065247, Contract No. W-271-Ord-971, Manufactured by the Massey Harris Company, Racine, Wisconsin	1-21-43
D-223-E-43	Test on Random Samples of R. M. S. Components as Manufactured by Delco-Remy	2-5-43
D-224-C-43	Pilot Inspection of Suppression as Applied to a Gasoline Operated Motor Compartment Heater, Model 203560, Serial No. 23295, Manufactured by Evans	1-29-43
D-225-C-43	Production Pilot Model Inspection of Suppression as Applied to Motorcycle, Model 741, Serial No. 22699, U.S.A. Registration No. 647492, Contract No. W-398-om-11749, mfd. by Indian Motorcycle Company	3-23-43
D-226-E-43	Status of Noise Suppression Cap. as Manufactured by the Sprague Specialties Company	1-29-43
D-227-C-43	Pilot Model Inspection of Suppression as Applied to Heavy Wrecker, Mod. M1, Serial No. 52331, USA Registration No. W-0015261, Contract No. W-883-ord-2716 Manufactured by the Kenworth Motor Truck Corporation	1-11-43
D-228-A-43	Installation of Radio Sets SCR-506-( ), SCR-508-( ), SCR-510-( ), SCR-608-( ), SCR-610-( ) and plans for Installation of Radio Sets SCR-193-( ), SCR-245-( ), as field Modifications in Light Armored Car M8 (Ford)	2-3-43
D-229-C-43	Production Pilot Model Inspection of Suppression as Applied to the Armored Car, T-17E1, Serial No. AC-1242-1152, USA Registration No. 6024989, Contract No. W-374-ORD-1315 Mfrd by Chevrolet Mtr Div (GMC), Flint, Michigan	1-20-43
D-230-E-43	Test on F. K. Mallory & Company's Random Samples of Radio Noise Suppression Components as Manufactured by J. E. Fast	2-5-43

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-231-E-43	Test on Random Samples of Radio Noise Suppression Components as Manufactured by P. R. Mallory	2-10-43
D-232-E-43	Test on Random Samples of Radio Noise Suppression Components as Manufactured by Tobe Deutschmann	2-5-43
D-233-E-43	Test on Random Samples of Radio Noise Suppression Components as Manufactured by Solar Manufacturing	2-5-43
D-234-C-43	Radio Interference Tests & Inspection of Armored Car T-18E2, Model 5001, Serial No. 003- Contract No. W-374-Ord-1401 & DRW-Ord-418, at the plant of the Yellow Truck & Coach, Pontiac, Michigan	2-5-43
D-235-C-43	Pilot Model Inspection of Suppression as Applied to the Medium Tractor, T-31, Model MG-3, Serial No. 1-LAX-000, Contract No. W-303-ord-971, Manufactured by the Cleveland Tractor Company, Cleveland, Ohio	1-18-43
D-236-D-43	Radio Interference Tests on Experimental Pilot Model Reconnaissance Truck with Power Take-Off Generator for Radio Equipment, 1/4 Ton, 4 x 4, Model GPW, USA Registration No. 2095535, Serial No. 193204, Contract No. W-303-ORD-2278, Manufactured by Willys-Overland Toledo O.	2-12-43
D-237-C-43	Production Pilot Model Inspection of Suppression as Applied to the 1 1/2 Ton, 4 x 2, Cargo Carrier, Model G8T, Serial No. 140072, Contract Numbers W-2425-qs-283 and W-374-Ord-2856, Manufactured by Ford Motor Company, Edgewater, N. J.	1-28-43
D-238-E-43	Life Test of Six RNE-CD Low Inductance Capacitor	2-9-43
D-239-E-43	Test on Production Samples of Radio Noise Suppression Capacitors as Manufactured by Delco-Remy Division	2-8-43
D-240-C-43	Production Pilot Model Inspection of Suppression as Applied to Medium Tank M4A1, Serial No. 10163, Contract No. W-883-ord-2544 at Pacific Car & Foundry	2-9-43
D-241-E-43	Test on random samples of Radio Noise Suppression Components as Manufactured by P. R. Mallory and Co.	2-10-43
D-242-E-43	Test on P. R. Mallory and Co. random samples of Radio Noise Suppression Components as Manufactured by John E. Fast Company.	2-10-43
D-243-E-43	Resistance Measurements of Track used on Buick 76 mm. Tank Destroyer	4-26-43

tion Components as Manufactured by Solar Mfg.

D-245-A-43	Pilot Installation of Radio Sets SCR-508-( ), SCR-506-( ), SCR-245-( ), British Wireless Set No. 19 & Interphone Equipment in Production Model of Light Tank M3A3 at American Car & Foundry, Berwick, Pennsylvania	2-15-43
D-246-C-43	Production Pilot Model Inspection of Suppression as Applied to the 5 Ton, 4 x 2, Model EM, Cargo Carrier, Serial No. E.H.I.D. 3978, Contract Nos. W-2425-qa-230 & W-670-ord-3191, Manufactured by Mack Corporation, Allentown, Pa.	2-16-43
D-247-D-43	Review of Radio Noise Interference Elimination and Radio Equipment Installation Observations in Surf Landing Boats at Engineering Amphibian Command, Camp Edward, Mass.	2-16-43
D-248-C-43	Production Pilot Model Inspection of Suppression as Applied to Medium Tank (Modified) M4, Serial No. 1576, Contract No. W-740-Ord-485, Manufactured by American Locomotive, Schenectady, New York,	2-11-43
D-249-E-43	Shock and Vibration Measurements in connection with Firing Test at the Proving Center, Aberdeen Proving Grounds, Aberdeen, Maryland	2-17-43
D-250-E-43	Test and Inspection of Experimental Tracks Utilizing Conductive Rubber Washers as a Means of Electrical Bonding	2-17-43
D-251-E-43	Corrosion resistance test on random sample of RNS Components as Manufactured by Solar Mfg. Corp.	2-17-43
D-252-E-43	CANCELLED	
D-253-E-43	Insertion loss measurements of low inductance capacitors with high current shunts. (See Memo #D-20-)	2-18-43
D-254-E-43	Insertion loss measurements of various capacitor networks	2-18-43
D-255-A-43	Installation Check of Zenith Sample Installation Kit. & British Wireless Set No. 19 in Armored Car T-17 by Ford Motor Company	2-19-43
D-256-A-43	Relocation of Radio Set SCR-593-( ) in Half Track Multiple Gun Motor Carriage M-15 (T-28E1) by Autocar Company	2-19-43
D-257-E-43	Test on Random Samples of Radio Noise Suppression Components, as Manufactured by Delco Remy Div., GMC	2-19-43

<u>MEMO NO.</u>	<u>SUBJECT</u>	<u>DATE</u>
D-258-E-43	Test on Random Samples of Radio Noise Suppression Components, as Manufactured by Tobe Deutschmann	3-19-43
D-259-D-43	Experimental Suppression on Generating Unit, Model No. M7, Contract No. W-374-ord-1774, Manufactured by Detroit Wax Paper Company, River Rouge, Michigan	2-20-43
D-260-E-43	Comparison of Tests performed on Mica & Paper di-electric Capacitors	3-26-43
D-261-C-43	Experimental Suppression on Generating Unit PE-95-F Model J.W.C. 58, Serial No. 21245C-2186, Manufactured by D. W. Onan & Sons, Minneapolis, Minne. Contract No. W-2124-SC-68-15-13142 Philadelphia 43	2-22-43
D-262-E-43	Test on a device for Coupling Feed Through & Standard Types of Capacitor to the Signal Generator & Receiver Terminating Net Works for Making Insertion Loss Measurements.	3-22-43
D-263-E-43	Test on Random Samples of Radio Noise Suppression Components as Manufactured by Sprague	2-23-43
D-264-D-43	Radio Interference Test on Dodge 1/2 Ton, 4 x 4, Radio & Recon. Car. U.S. No. 608980, Model W.C. 25 Manufactured by Dodge Truck Co.	2-25-43
D-265-E-43	Test on Production Samples of Radio Noise Suppression Capacitor as Manufactured by Sprague Specialties Manufacturing Company, and Submitted by Indian Motorcycle Company.	3-22-43
D-266-A-43	Service Test Installation of Radio Set SCR-509-( ) and Radio Set SCR-510-( ) less portable components in experimental model 81 mm mortar motor carrier M4A1, USA Registration No. 4015367	2-26-43
D-267-E-43	Test on Production Samples of Radio Noise Suppression Capacitors, as Manufactured by Evans Products Co.	3-30-43
D-268-E-43	Test on Random Samples of Radio Noise Suppression Components, as Manufactured by Delco-Reay Division	2-26-43
D269-E-43	Test on Production Samples of Radio Noise Suppression Capacitors, as Manufactured by P. R. Mallory & Company	3-1-43
D-270-E-43	Test on Design Sample Filter, as Manufactured by P. R. Mallory and Company	4-12-43
D-271-C-43	Production Pilot Model Inspection of Suppression as Applied to Light Tank M3A3, Serial No. 84, Contract No. W-670-ORD-2014, Manufactured by American Car & Foundry, Berwick, Pennsylvania	2-18-43

<u>MEMO NO.</u>	<u>TITLE</u>	<u>DATE</u>
D-272-E-43	Corrosion Test on Filter Terminals Manufactured by Solar Manufacturing Corporation	3-2-43
D-273-E-43	CANCELLED	
D-274-E-43	Application of Suppression components to the King Seeley Automotive Gauge for Radio Interference elimination.	3-5-43
D-275-E-43	Test on production samples of Radio Noise Suppression capacitors, as Manufactured by Delco Remy Div.	3-25-43
D-276-A-43	Revised Pilot Installation of Radio Set SCR-510-( ) and Interphone System RC-99 in Light Tank T9E1 (Marmon-Herrington)	3-8-43
D-277-A-43	Preliminary Provisions for the Installation of Radio Set SCR-610-( ) and Interphone Equipment RC-99 in British Wireless Set No. 19 in a wood Mock up of 76mm Gun Motor Carriage T70 (Buick)	3-15-43
D-278-E-43	Test on Production Samples of Radio Noise Suppression filters, as Manufactured by P. R. Mallory & Co. Inc.	3-22-43
D-279-E-43	Test on Production Control Samples of Radio Noise suppression filters, as Manufactured by Delco-Remy Division-General Motor Corp.	3-11-43
D-280-A-43	Installation of Radio Sets SCR-506-( ), SCR-608-( ) & SCR-610-( ) in Armored Command Car T-26 (Ford Mo. Co.)	3-16-43
D-281-C-43	Pilot Model Inspection of Suppression as Applied to the 1½ Ton, 4 x 4, Model No. G7128, Bomb Service Truck, Serial No. 9NQL3-7394, Contract No. W-374-ord-2216, Manufactured by Chevrolet Motor Division of GMC Norwood, Ohio	3-10-43
D-236-d-s-43	Additional Suppression components necessary to Suppression power-take off Generator for Radio Equipment, Truck ½ Ton, 4 x 4, Contract No. W-393-Ord-4278, Manufactured and shipped by Willys Overland Company	3-13-43
D-156-c-s-43	Mechanical Changes in Applying the Suppression in Eng. Memo d-156-c-43 re 4 Ton, 4 x 4, Rec. Truck with Radio Terminal box Mod. gpw Cont. No. W-398-qa-13117 Manufactured by Willys-Overland	3-15-43
D-282-A-43	Revision of Provisions for the Installation of Radio Set SCR-510-( ) in Car, ½ Track M9. (International Harvester)	3-17-43